



EuCertPlast

## Summary Sheet

Certificate Number: 0131-10-19-CYC-TD

**Type of Certification: Annual monitoring audit – Full certificate**

For the recycling plant:


**bage plastics GmbH**

Recycling plant: Hainbach 14, **4493 Wolfern**

Extrusion: Eisenstraße 96, **4502 St. Marien**

**Austria**

Recycling process	Input plastic waste (type of material)	Presentation	Nominal capacity (t/a)	Post-consumer material accepted for recycling in previous 12 months (t)	Recycled output (type of material)	Post-consumer recycled output (t)	Pre and post-consumer recycled Output (t)	Level of traceability (1 to 3)	Washed material
Mechanical recycling/ final recipient	WEEE (mixture of PP – rigid, PS – rigid, ABS – rigid, PC – rigid)	Bulk material (shredded)	Wolfern: 22.400 St. Marien: 16,600	17,626	PP-, PS-, ABS-, ABS/PC-pellets/grinding stock	12,296	15,587	2	Y

Audited by:	Thomas Döpelheuer	<b>Auditor's logo:</b>  cyclos GmbH Westerbreite 7 49084 Osnabrück, GERMANY Phone: +49 541 77080-0 Fax: +49 541 77080-99 thomas.doepelheuer@cyclos.de
Date of audit:	13 September 2018	
Period of evaluation:	01/09/2017 to 31/08/2018	
Period of validity:	06/10/2018 to 05/10/2019	
Recycler contact:	Philipp Baum baum@bage-plastics.com	

The recycling process and associated management systems of the aforementioned company for the waste plastic and site shown has been audited and have met the required standards for certification under the EuCertPlast Scheme for European Plastic Recyclers

This plant is the last recipient of plastics waste and produces products.

Osnabrück, 5 October 2018

Thomas Döpelheuer



Publicly certified expert on packaging disposal, appointed by the chamber of commerce and industry  
Competent: chamber of commerce and industry Osnabrück – Emsland – Grafschaft Bentheim

EuCertPlast c/o EuPR, Avenue de Cortenbergh 71, 1000 Brussels, BELGIUM

[www.eucertplast.eu](http://www.eucertplast.eu)



EuCertPlast

## Summary Sheet


Certificate Number: 0131-10-19-CYC-TD

*Type of Certification: Annual monitoring audit – Full certificate*

For the recycling plant:

**bage plastics GmbH**  
 Recycling plant: Hainbach 14, **4493 Wolfern**  
 Extrusion: Eisenstraße 96, **4502 St. Marien**  
**Austria**

Recycling process	Input plastic waste (type of material)	Presentation	Nominal capacity (t/a)	Post-consumer material accepted for recycling in previous 12 months (t)	Recycled output (type of material)	Post-consumer recycled output (t)	Pre and post-consumer recycled Output (t)	Level of traceability (1 to 3)	Washed material
Mechanical recycling/ final recipient	WEEE (mixture of PP – rigid, PS – rigid, ABS – rigid, PC – rigid)	Bulk material (shredded)	Wolfern: 22.400 St. Marien: 16,600	17,626	PP-, PS-, ABS-, ABS/PC-pellets/grinding stock	12,296	15,587	2	Y

Audited by:	Thomas Döpelheuer	<b>Auditor's logo:</b>  cyclos GmbH Westerbreite 7 49084 Osnabrück, GERMANY Phone: +49 541 77080-0 Fax: +49 541 77080-99 thomas.doepelheuer@cyclos.de
Date of audit:	13 September 2018	
Period of evaluation:	01/09/2017 to 31/08/2018	
Period of validity:	06/10/2018 to 05/10/2019	
Recycler contact:	Philipp Baum baum@bage-plastics.com	

The recycling process and associated management systems of the aforementioned company for the waste plastic and site shown has been audited and have met the required standards for certification under the EuCertPlast Scheme for European Plastic Recyclers

This plant is the last recipient of plastics waste and produces products.

Osnabrück, 5 October 2018

Thomas Döpelheuer



Publicly certified expert on packaging disposal, appointed by the chamber of commerce and industry  
 Competent: chamber of commerce and industry Osnabrück – Emsland – Grafschaft Bentheim

EuCertPlast c/o EuPR, Avenue de Cortenbergh 71, 1000 Brussels, BELGIUM

[www.eucertplast.eu](http://www.eucertplast.eu)